




Atera SIGNO

Audi
A5 Sportback (B9/F5) 02/2017–






nur bei / only for Part-No.: 045 347



Atera SIGNO

Audi
A5 Sportback (B9/F5) 02/2017–

Art.-Nr. / Part-No. : 044 347
Art.-Nr. / Part-No. : 045 347



Atera
MADE IN GERMANY


Atera GmbH
Im Herrach 1
D-88299 Leutkirch
Internet: www.atera.de





© ATERA GmbH
Ref.-Nr.: 044 347_096454434700_992570050200
Ref.-Nr.: 045 347_096454534700_992570050200
Stand/State: 14/06/2017 – Rev 00 Ver 00

Atera SIGNO

Audi
A5 Sportback (B9/F5) 02/2017–



INFO



Atera SIGNO

Audi
A5 Sportback (B9/F5) 02/2017–

