






Atera SIGNO

BMW
5-er Limousine (F10) 03/2010–02/2017






nur bei / only for Part-No.: 045 173



Atera SIGNO

BMW
5-er Limousine (F10) 03/2010 – 02/2017

Part-No. : 044 173
Part-No. : 045 173



Atera
MADE IN GERMANY





Atera GmbH
Im Herrach 1
D-88299 Leutkirch
Internet: www.atera.de



© ATERA GmbH
Ref.-Nr.: 044 173_060 860
Ref.-Nr.: 045 173_060 860
Stand/State: 06/02/2019 – Rev 00 Ver 03

Atera SIGNO

BMW
5-er Limousine (F10) 03/2010–02/2017



Atera SIGNO

BMW
5-er Limousine (F10) 03/2010–02/2017

